


EXISTING ROOF



COVE MOLD  
- REMOVE &  
VERIFY SECTION  
IF NEEDED


1 1/2"  $\phi$  DOXELING

SECTIONS OF WOOD  
STRIPPING & PIECES  
OF COVE MOULDING  
APPEAR TO BE DRY ROTTED  
OUT AND ON SITE INSPECTION  
MAY INDICATE THAT  
SOME AREAS MAY NEED  
TO BE REPLACED DURING  
PAINTING

NOTE: MOST PAINT HAS  
WEATHERED AWAY OR  
REMAINS IN LARGE FLAKES


### FASCIA @ EAVE

SCALE: 3" = 1'-0"



WHEELER STALLARD HOUSE  
EXTERIOR RENOVATION & REPAIRS

CHARLES CUNIFFE & ASSOCIATES/ARCHITECTS



ASPEN, COLORADO P.O. BOX 3534, ASPEN, COLORADO 81612 TELEPHONE 303/925-5590